TEST REPORT

Scan to see the report

QDIN2408001532PL01
Verification:
check.sgsonline.com.cn

No. : QDIN2408001532PL01_EN

Date : 2024-09-06

CUSTOMER NAME: QINGDAO JUMBO INTERNATIONAL TRADE CO.,LTD

ADDRESS: NO.33A06, EAST HALL, YIHE BUILDING A, NO.10 HONG KONG MIDDLE ROAD, SOUTH DISTRICT, QINGDAO, CHINA

Sample Name : Texture HDPE Board

Manufacturer : Qingdao Jumbo International Trade Co.,Ltd

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

****

Date of Receipt : 2024-08-08

Testing Period : 2024-08-08 ~ 2024-09-03

Test result(s) : For further details, please refer to the following page(s)
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical
Services (Qingdao) Co., Ltd..

Kayla Chu

Kayla Chu
Authorized signatory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS Center, No.143, Zhuzhou Road, Laoshan District, Qingdao, Shandong, China 266101
中国·山东·青岛市崂山区株洲路143号通标中心 邮编：266101
t (86-532) 68999888 www.sgsgroup.com.cn
t (86-532) 68999888 sgs.china@sgs.com

TEST REPORT

No. : QDIN2408001532PL01_EN

Date : 2024-09-06

Summary of Results:

No.	Test Item	Test Method	Result	Conclusion
1	Light Ageing Test-UV Exposure	ISO 4892-3:2016 cycle 1 & ISO 105-A02:1993/Cor.2:2005	See result	See result

Note: Pass : Meet the requirements;

Fail : Does not meet the requirements;

N/A : Not Apply to the judgment.

Original Sample Photo:



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS Center, No.143, Zhuzhou Road, Laoshan District, Qingdao, Shandong, China 266101 t (86-532) 68999888 www.sgsgroup.com.cn

中国·山东·青岛市崂山区株洲路143号通标中心 邮编：266101 t (86-532) 68999888 sgs.china@sgs.com

TEST REPORT

No. : QDIN2408001532PL01_EN

Date : 2024-09-06

Test Item: Light Ageing Test-UV Exposure

Sample Description: See photo

Test Method: ISO 4892-3:2016 cycle 1 & ISO 105-A02:1993/Cor.2:2005

Test Condition:

UV Exposure cycle: cycle 1

Lamp type: UVA-340

8h UV at (60±3)℃ BPT, 0.76W/(m^2•nm)@340nm

4h condensation at (50±3)℃ BPT

Exposure duration: 400h

Test Result:

Test Item	Test Result	Client's Requirement	Conclusion
Light Ageing Test-UV Exposure	Grey scale: 5	≥4	Pass
	Appearance :No significant changes	/	/

Note:

1. According to ISO 105-A02:1993/Cor.2:2005, the grey scale was determined under the D65 standard light, with scale 5 as the best and scale 1 as the worst.
2. The results were carried out within 1 hour after above specified durations for the intermediate inspection as well as at the end of the exposure.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS Center, No.143, Zhuzhou Road, Laoshan District, Qingdao, Shandong, China 266101 t (86-532) 68999888 www.sgsgroup.com.cn

中国·山东·青岛市崂山区株洲路143号通标中心 邮编：266101 t (86-532) 68999888 sgs.china@sgs.com

TEST REPORT

No. : QDIN2408001532PL01_EN

Date : 2024-09-06

Test Photo:

	
Reference specimen Test specimens Before test	Reference specimen Test specimens After test

Equipment Information:

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Accelerated Weathering Tester	QUV/se	POL-AG-E035	2024-07-15	2025-07-14
Spectralight QC	SpectraLight QC	POL-AG-E018	2024-07-15	2025-07-14

********End of report********

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS Center, No.143, Zhuzhou Road, Laoshan District, Qingdao, Shandong, China 266101 t (86-532) 68999888 www.sgsgroup.com.cn
中国·山东·青岛市崂山区株洲路143号通标中心 邮编：266101 t (86-532) 68999888 sgs.china@sgs.com